


WBT MR4 Instructions






3,5,7
mm



≈15 min


	-16	-16T	-17	-17T
WBT10	24.54	24.05	25.15	24.66
WBT12	27.12	26.59	27.74	27.20
WBT14	29.71	29.13	30.33	29.75
WBT16	32.31	31.68	32.92	32.30



10mm




5mm




L311WB

x 2




SW50X

x 1




SW50X

x 1




MS1867L

x 1




MS1867R

x 1



WT40

x 1




MS202X

x 1




SHL3XX

x 1



L30X


x 2



FN003

(M6)


x 21



FN001

(M6)


x 4



FW001

(M6)


x 12



FW004

(M6)


x 21



FW011

(M6)


x 17



FS188

(M6x16)


x 8



FS233

(M6x16)

x 13



FS180


(M6x35)

x 4



FS305







x 12




PS259

x 4







7.




8.




9.




10.




11.




12.




13.




14.




15.




16.




17.




18.




19.




20.




21.




22.




23.




24.



25.



26.



27.

